






[LANCIA](#) / [YPSILON](#) / [1.3 JTD](#) / [PROCEDURES](#) / [70 FITTINGS](#) / [7005 PASSENGER COMPARTMENT FRONT SIDE DOORS](#)
/ [7005E FRONT SIDE DOOR TRIM](#) / 7005E12 CORNER COVER OF ONE FRONT SIDE DOOR, LH OR RH R R

2429507 - 7005E12 corner cover of one front side door, lh or rh r r

 Removing ([Refitting](#) )

1. Release the trim (1a) releasing the retainers (1b).



 Refitting ([Removing](#) )

Check that the trim and the retainers are not damaged.

Fit the trim attaching the retainers.