


[LANCIA](#) / [YPSILON](#) / [1.3 JTD](#) / [PROCEDURES](#) / [70 FITTINGS](#) / [7005 PASSENGER COMPARTMENT FRONT SIDE DOORS](#)


/ [7005M FRONT ELECTRIC WINDOWS](#)

/ 7005M28 FRONT SIDE DOOR ELECTRICALLY OPERATED WINDOW MOTOR - R R WITH DOOR PANEL-MOUNT FRAME REMOVED

2429514 - 7005M28 front side door electrically operated window motor - r r with door panel-mount frame removed

 Refitting ([Refitting](#) )


1. Disconnect the electric window motor connection.



 Name	Connector
1 Driver's front electric window motor	N60

 Name	Connector
1 Front passenger side electric window motor	N61

2. Undo the bolts.

3. Remove the motor releasing the splined shaft.



 Refitting ([Removing](#) )

Check that the motor is undamaged.

Connect the electrical connection.

Position the motor and secure with bolts.