

[LANCIA](#) / [YPSILON](#) / [1.3 JTD](#) / [PROCEDURES](#) / [72 PANELS AND FRAME](#) / [7205 STRIPPING FOR REPLACEMENT OPERATIONS](#)
/ [7205E EXTERIOR PARTS](#) / 7205E37 STRIPPING FRONT SIDE DOOR INNER SUPPORT FRAME

2429708 - 7205E37 STRIPPING FRONT SIDE DOOR INNER SUPPORT FRAME

Refer to op.. [7005C44 interior handle panel - r r](#)

Refer to op.. [7005M11 Driver's front door electric window control SWITCH - R.R.](#)

Refer to op.. [7005M12 passenger side front door electrically operated window switch - r r](#)

Refer to op.. [7005E12 corner cover of one front side door, lh or rh r r](#)

Refer to op.. [7005E08 front side door interior panel r r](#)

Refer to op.. [7005D14 front side door descending window glass - r r with door panel \(and mount frame\) removed](#)

Refer to op.. [7005A08 interior support frame of one side door r r with door panel removed](#)

Refer to op.. [7005M28 front side door electrically operated window motor - r r with door panel-mount frame removed](#)

Refer to op.. [5570T90 front speaker - r r](#)

Refer to op.. [5580T11 bose sound system front speaker \(one\), lh or rh - r r with door panel removed](#) (alternative)

Refer to op.. [5505A43 \(DIGITAL NETWORK\) CONTROL UNIT IN DRIVER'S DOOR -R.R. WITH PANEL REMOVED](#)

Refer to op.. [5505A47 \(Digital network node\) CONTROL UNIT in passenger door - R.R. with panel removed](#) (alternative)

Refer to op.. [7005C50 front side door interior opening mechnism r-r for repair or replacement with door panel removed](#)

Refer to op.. [7005N20 front side door lock motor/catch assembly - rr with door panel and support frame removed](#)

Refer to op.. [5505B10 front door wiring - r r](#)

Refer to op.. [7005M27 ELECTRIC 'WINDOW OPENING MECHANISM FOR ONE FRONT DOOR, LEFT OR RIGHT - R.R. WIWTH SUPPORT FRAME REMOVED](#)

Refer to op.. [7005C52 interior opening handle - r r](#)

1. Prise up both covers
2. Recover the frame (2a) with gasket (2b).

